North Dakota Department of Health

Division of Laboratory Services - Chemistry

Original Report Date: 7/29/14 Report Date: 7/29/14

Log Number: 14-C445

Date Collected: 7/24/14 Date Received: 7/24/14 Time Collected: 9:32 Time Received: 16:00

Township: Range: Section: Owner:

Source: Red River #3

Project: RROSWF Red River Oil Serv. Williston Fire

Comments: 48.146392-103.598411 Relief channel east of site

ATTN DAVE GLATT EHSC - HL12622 GOLD SEAL BUILDING

GOLD SEAL BUILDING 918 E DIVIDE AVE BISMARCK ND 58501

proved by:

Organic

Approved by

Inorgan

Analyte	Chemical Analysis of Result	Sample Units	Evaluation
Conductivity Dissolved Solids(C)-To Alkalinity (CaCO3)(To pH Carbonate (CO3) Bicarbonate (HCO3) Fluoride (F) Hydroxide (OH) Turbidity		umhos/cm mg/L mg/L mg/L mg/L mg/L mg/L	Fairly Low Low

NOTE: This report represents the current state of work in progress.

Additional analyses may change some of the results reported.

Statement: This analysis includes chemical content only, and does not determine the bacterial quality of the water.

For further information contact:
North Dakota Department of Health
Division of Laboratory Services - Chemistry
Box 5520
Bismarck, ND 58506-5520
(701) 328-6140